

SPECTRA PREMIUM **FUEL FILLER NECKS**

THE PREMIUM CHOICE

NOW IN INVENTORY

- MAJOR CAUSE OF "EVAP" CODE ERROR
- DUAL COATED FOR ENHANCED CORROSION PROTECTION
- PREVENT EXPENSIVE FUEL LEAKS AND UNNECESSARY COMEBACKS
- BE PROACTIVE! AVOID UNNECESSARY FUEL PUMP FAILURE



OK TIRE™

Honestly driven.

www.OKTireWindsor.com
Owned & operated by the Santing Family since 1958

**SPECTRA
PREMIUM**™
forming the future

WINDSOR ONT.
3666 WALKER ROAD, NBW 3S7
TEL.: 519-966-0422
E-MAIL: INFO@SANTINGOKTIRE.COM